


| Job Name: 36840 Red Berry Rd. Delmar, DE | Inspection Date: 1/23/2020 |
|--|--|
| Name of Property Owner/Seller/Purchaser/Other: | Inspector's Name: Andrew Lewandowski |
| Gerald Shockley | Inspector's Phone Number: 302-200-7663 |

| Main Roof | Material: Shingles/Metal Roof | Roof Design:Hip Roof |
|---|-------------------------------|------------------------------|
| Estimated Square Footage: | Estimated Age: less than one | Estimated Remaining Life: 50 |
| unknown | year | years |
| After the metal roofing was installed, siding and shingle roof installers left gaps between their shingles, | | |
| soffit, fascia and siding. These gaps could allowed water to enter the house. | | |


Below are images and descriptions of the issues caused by incorrectly installed shingles, siding, soffit and fascia.





Ridge Cap cut back from the wall by siding installers. (Done by Others)

Can be corrected for \$160.00






J-Channel needs to be tight to the metal roof to keep water and animals out. (done by others)

There is nothing wrong with how the metal meets the shingles. (Shingles were installed by others after metal roof was installed)







Soffit and J-Channel needs to be cut around metal roof to close gap. This is needed to keep water and animals out.(done by others)





J-Channel needs to be tight to the metal roof to keep water and animals out. (done by others)



Listing of repairs needed: Replace Hip cap that was cut short by siding installers \$160.00. Soffit, fascia, shingles and siding was installed short leaving gaps above the metal roofing.(these items were installed by others and needs to be corrected)

Additional Comments: Previous inspection report has incorrect information about the placement of butyl tape per manufactures instructions. The report has wrong information about the closures used where the metal roof meets the walls. Attached are drawing provided by Drexel Metals showing the CFR trim that was used per Drexel Metals specs and the placement of butyl tape in the valley detail. Bayside Exteriors is more than happy to work with any other contractor to help resolve these isses.










VALLEY DETAIL







Additional notes: Everything was explained and communicated before and during the metal roof install.(questions regarding the metal returns, explanations of the CFR trim and concerns about other contractor's workmanship)

Bayside Exteriors was not told about any problems with the roof until after this project was sent to collections for failing to pay final payment.


See attached Images between Craig Cameron from Bayside Exteriors and Gerald Shockley



Explanation about how the soffit must be installed



Site meeting with Gerald's brother Kenny to show problems with shingle roof install



Explanation of CFR Trim



ⁱ "Metal Trim Details Standard and Custom." *Drexel Metals*, Drexel Metals, Inc. , 2014, www.drexmet.com/sites/drexmet.com/files/met-fab/Trim Catalog Rev11.pdf.

[&]quot; "CFR Detail." CFR Detail, 25 Nov. 2019.

[&]quot;Slide Share." Slide Share, Drexel Metals, Inc., 6 June 2013, https://www.slideshare.net/drexelmetals/drexel-metals-aia-making-the-educated-choice-metal-roofing-2013.