Cheikin\_Restoration\_Group\_2023\_04\_02\_Notes p1

O&P = Overhead and Profit; RCV = Replacement Cost Value; ACV- Actual Cash Value

#### **WORK AUTHORIZATION PAGES 1-2**

Reasonable Start and End Dates

Addendum to Contract

**Insurance and License Certificates** 

**Permits** 

Responsibility for Sub-Contractors

Names of all Subs

Project Manager employee of TRG

Additional Work (supplements): Empty Pod, Disinfect Pod

**Disinfect Appliances** 

Mattresses, possibly frames (in Pod)

Registers

Pod Rental

Paint--Benjamin Moore Brand, allowance per gallon?

Corner Bead--whole house? Curved?

#### **PROJECT SPECS 19 PAGES**

#### General

**Completion of demolition**: two tubs, bathroom counter, fireplace marble footer

sections of drywall esp w old tile

remove/dispose old doors

Cleaning of existing fixtures, windows, etc.

Garage--paint, clean

### Master Bedroom p 1

26. More than one register

27. Ceiling Fan Replacement Value

```
Cheikin_Restoration_Group_2023_04_02_Notes p 2
   28. Blinds--3 sets, not 1
   Magnetic door latch (removed w molding)
Master Bath, Closet and Toilet p 4
   29. Hollow door $341?
   31. Texture vs Skim Coating?
   41. Floor in bathroom is tile, not vinyl planking
      Closet had carpet
   51. Tile--materials vs labor?
   58. Shower door-materials vs labor? Custom size? Wall?
   Medicine cabinet?
   Missing Casing
   Missing Blinds for Window (approx 4-5 feet)
   Using old faucets for sinks, tub and shower?
   70. Kickspace Heater--replacement--subject to moisture.
Hall and Closet p 5
   Missing Casing?
   Missing large register approx 2 ' x 3 '
Kitchen including Nook p 5 of 19
   101. Cabinetry adding to ~25k, order w Atlantic for matches
   108. Hood shank dented by prior contractor-how to address?
   110. Oven-double sized, will need cabinet mods
   112. Copper sink may be damaged
   117. Plumbing "left open"-- close up with vapor barrier (after proper testing)
      Install Reverse Osmosis
      ? Replace Reverse Osmosis (parts discarded?)
```

Install water line to refrigerator

```
Cheikin_Restoration_Group_2023_04_02_Notes p 3
      Fitting for the outside spigot
   120. 3 Blinds already included (nook)
   Laundry Room 7 of 19
      Magnetic Door Latch (removed w molding)
   Guest Bathroom p 11 of 19
      Sink fixture
      Bath/shower fixture (line 206 is the install)
   Library (Office) 11 of 19
      Blinds are approx 5' wide
      Remove and re-install chandelier?
   Bed 1 (Guest) and closet (Subroom Room 11) p 12 of 19
      Blinds are approx 5' wide
      Remove and re-install chandelier?
   Living Room (= Middle Rm + Family Rm )p 14-15 of 19
      275, 6, 7 Three blinds
      Corner Bead
      284.5 Four blinds for "living rm"
```

## Blinds: Total of 20:

Nook 7

Family 5

Middle 2

Library 1

Guest 1

Master Bedroom 3

Master Bathroom 1

# **Blinds on Proposal**

28 Master Bedroom 1

120 Kitchen 3

232 Office 1

255 Guest Bedroom 1

275,6,5 Living Rm 6

284 Living Rm 4

285 Living Rm 3

TOTAL: 19

Cheikin\_Restoration\_Group\_2023\_04\_02\_Notes p 5